

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: TN2802	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 07/02/2021
NAME OF PROVIDER OR SUPPLIER AHC MEADOWBROOK		STREET ADDRESS, CITY, STATE, ZIP CODE 1245 E COLLEGE ST PULASKI, TN 38478		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{N 000}	Initial Comments A Life Safety Code Follow up Survey was conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulations Office of Health Care Facilities on 7/2/2021. During this Life Safety Code Follow Up Survey, AHC Meadowbrook was found in substantial compliance with the requirements of the Tennessee Rules and Regulations 1200-08-06, Standards for Nursing Homes, and National Fire Protection Association (NFPA) 101 Life Safety (2012 Edition).	{N 000}		

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: TN2802	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/09/2021
NAME OF PROVIDER OR SUPPLIER AHC MEADOWBROOK		STREET ADDRESS, CITY, STATE, ZIP CODE 1245 E COLLEGE ST PULASKI, TN 38478		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 000	Initial Comments Stories: 1 Construction Type: NFPA, III (200); IBC, III unprotected Limited plans available on site Constructed: 1970s Sprinklered: Yes A Life Safety Code Survey was conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulations Office of Health Care Facilities on 6/7/2021. During this Life Safety Code Survey, AHC Meadowbrook was found not in substantial compliance with the requirements of the Tennessee Rules and Regulations 1200-08-06, Standards for Nursing Homes, and National Fire Protection Association (NFPA) 101 Life Safety (2012 Edition).	N 000		
N 831	1200-8-6-.08 (1) Building Standards (1) A nursing home shall construct, arrange, and maintain the condition of the physical plant and the overall nursing home environment in such a manner that the safety and well-being of the residents are assured. This Rule is not met as evidenced by: Based on observations, the facility failed to maintain the physical plant and the overall nursing home environment. The findings included: Observation on 6/7/2021 at 1:00 PM, revealed unsealed penetrations in the following locations:	N 831		

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

Jeannette M. Raymer, LNHA
G89X21

6-25-2021

If continuation sheet 1 of 2

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: TN2802	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/09/2021
NAME OF PROVIDER OR SUPPLIER AHC MEADOWBROOK		STREET ADDRESS, CITY, STATE, ZIP CODE 1245 E COLLEGE ST PULASKI, TN 38478		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 831	Continued From page 1 Data closet inside Social Services office a.(1)-NM electrical cable (ceiling) b.(18+)- low voltage cables (ceiling) National Fire Protection Association, NFPA 101, 8.3.5 (2012 Ed.), NFPA 101,8.3.5.1(2012 Ed.) The Maintenance Director was present when these findings were identified, and it was acknowledged by the Administrator during the exit conference on 6/7/2021.	N 831	N- 831 1.Administrator contacted IT department to assist with correcting penetration concerns. 2.The data/telephone room was the only area affected by this deficient practice. 3.After area is properly sealed Maintenance Director will inspect for proper seal. 4.Maintenance Director will audit the affected area weekly for 4 weeks then monthly for 2 months to maintain compliance. All results of audits will be brought to the QAPI Committee which consists of the DON,Administrator, Medical Director and ICP. Any concerns will be addressed immediately, and any trends will be discussed.	